

T 0 F T 0 2 0 " 5 C T 0 0 6 6 0






FIG. 3






FIG. 4




FIG. 5

418

FIG. 6
THERMOFORMING PROCESS







FIG. 6

518



6/8




FIG. 10




FIG. 11




FIG. 12




FIG. 13

7/8

T 00 T T E 00 " G 00 T T 00 G 00




FIG. 14




FIG. 15